

SECRET

out 67908

23 JUN 69 17 30z

S E C R E T 231724Z JUN 69 CITE [] 6549

25X1

25X1

SUBJ: EVALUATION OF GLASS LAMP MISSION G-086

1. IMAGE QUALITY: THE IMAGE QUALITY OF THIS MISSION RANGES FROM FAIR TO GOOD. THE IMAGERY VARIES WITHIN THE FORMAT WITH THE POORER IMAGERY LOCATED ALONG BOTH FORMAT ENDS AND THE OUTBOARD EDGE. THE INTERPRETABILITY SUITABILITY AND GROUND RESOLUTION ARE FAIR TO GOOD. CLOUD COVER AND HAZE OBSCURE APPROXIMATELY 20 PERCENT OF THE ENTIRE MISSION.

2. MISSION DATA

- A. G-086
- B. 19 JUNE 1969
- C. B/10/U2R
- D. MODE 5
- E. T/O 1030Z, C/ON 1221Z
- F. 3401
- G. 1/360
- H. F/10
- I. WRATTEN 12 (MINUS BLUE)
- J. NAV RECON TECH SUPPCEN, MX578

DISTRIBUTION		
CY	OFFICE	PI
1	FILE	
	CABLE SEC.	
	PP&B/RD	
	SECUR.	
2	TSSG/ABSD	✓
	FSL MC	
	RND	
	REFRO	
	ATD	
	LEG	
	PROD	
	SCIEN	
	WEST	
	EAST	
	M&S	
	PGM	
	MEDIAS	
	END DIA-XX4	
	SPAD	
	DIA-AF	
	CMX	

PAGE 2 [] 6549 S E C R E T

25X1

K. LEFT SIDE: 2.20; RIGHT SIDE: 2.22

3. ORIGINAL NEGATIVE

A. EXPOSURE: ADEQUATE FOR INTERPRETATION.
 B. DENSITY AND CONTRAST: THE DENSITY RANGES FROM MEDIUM AS IN THE BEGINNING OF THE MISSION TO SLIGHTLY HEAVY AT THE END OF THE MISSION. THE CONTRAST IS GENERALLY MEDIUM.

C. IMAGE DEGRADATIONS

1. BOTH SIDES: MINOR INBOARD AND OUTBOARD EDGE FOG AND INBOARD ROLLER CHATTER ARE PRESENT THROUGHOUT THE MISSION.

D. PHYSICAL DEGRADATIONS

1. 9R SIDE: SEVERAL PROCESSING STREAKS ARE PRESENT FROM FRAME 1150 TO THE END.

2. BOTH SIDES: NINE HEAT SPLICES AND ONE MANUFACTURE SPlice ARE PRESENT ON EACH OF THE SIDES.

E. AUXILIARY DATA: THE FRAME COUNTER FAILED TO REGISTER FOUR TIMES DURING THE MISSION. ALL OTHER DATA RECORDING SYSTEMS FUNCTIONED PROPERLY.

4. POSITIVES: PRINTING AND PROCESSING ARE GOOD.

S E C R E T

ADVANCE CY
 SANITIZED
 WITH TEXT

25X1

END OF MESSAGE

SECRET

GROUP 1
 Excluded from automatic
 downgrading and
 declassification